

PHENIX WEEKLY PLANNING 10/16/2008 Don Lynch



Technical Support 2008

IR Configuration for remainder of shutdown

October November December January

5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

Station 1 north access now-10/17 (Current Configuration:

CM & MMS south WC west

Run Position 10/20 - 10/31 (CM & MMS moved north WC west)

Station 1 south access 11/3-12/12 (MMS moved south WC west)

Station 1 north access 12/15-12/31 (CM moved south, WC west)

East Carriage Install 1/2-1/15 (CM moved north, EC & WC opt.)

Run Position 1/16-1/19
(MMS moved north, EC & WC opt)

Ready for run 9 1/19-2/1
(MuID Collars Installed, EC & WC opt.)
10/16/08

Technical Support 2008

October November December January

5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

Station 1 north access now-10/15 (Current Configuration:

CM & MMS south WC west

Install & test Sta. 1 N cards

-----DONE----

Remove Sta 1 N scaffold 10/16-10/17 -



October November December January

5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

Run Position 10/15 - 10/31 (CM & MMS moved north WC west)

Move CM & MMS north 10/20-10/21

MuTrigger 5 rack ass'y < DONE>

RPC proto rack assy by 10/15

water & Elec prep 10/17-10/31 ----

RPC2 proto gas system by 10/31

RPC proto cable by 10/31 routing & support

Install RPC2 prototype 10/20-10/31

PC1 West repairs 10/20-10/31

Shutdown '08 Schedule

October November December January

5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

Station 1 south access 11/3-12/12 (MMS moved south WC west)

Move MMS south

11/2

Install sta 1. S Scaffolds 11/3-11/7

HBD Installation (west) 11-3-11/10 (east) 12/17-12/31

MuTrigger FEE 11/10-11/14

Sta 1 S chasis install

Sta 1, 2 & 3 chasis 11/10-11/14

Water & air

Install/test cards 10/2-11/30

sta 2&3 N and sta 1, 2 & 3 S

Install Lead absorber 11/17-11/21

Install FEE S rack platform 11/17-11/21

And racks

FEE S Cabling & Testing 11/24-11/29

MuTr sta 1 5 Decaps 12/1-12/12

10/16/08

→



October November December January

5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

Station 1 north access 12/15-12/31 (CM moved south, WC west)

Remove Sta 1 S 11/24-12/18 And Sta 2/3 N scaffolds

Move CM south 12/18

Install MMS lampshade 12/18-12/21

Install MMN lampshades12/18-12/31

October November December January

5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

East Carriage Install 1/2-1/15 (CM moved north, EC & WC opt.)

Install EC 1/2-1/15

Run Position 1/16-1/19 (MMS moved north, EC & WC opt)

Move MMS North 1/16

Ready for run 9 1/19-2/1 (MuID Collars Installed, EC & WC opt.)

DC East/West Repairs 1/16-2/1

Install MuID Collars 1/19-1/21

Pink/Blue/White Sheets 1/16-2/1

Close Shield Wall 126-1/30

Cryo Start Up, Start Physics 2/1-2/18

10/16/08



October November December January 5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

Other On going Tasks

RPC3 Prototype install (by 12/31) (including assembly at factory, Moving tunnel shielding, modify Crystal palace & vapor barrier,

Fan Tray Mainteance (fill in)

RPC Factory Support

Dark Current test stand

Storage Racks with humid. Cntrl

RPC3 install, rack, services & testing)

Prep for 2009 Shutdown (as time permits)

Gas Mixing house UPS by 11/30




October November December January

5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25

Rack room electronics, etc.

Build new storage 10/1-11/15 crates

NCC prototype design support HBD support VTX fabrication tooling design VTX installation design FVTX design/engineering support



As Required

PH ** ENIX

Shutdown '08 Electrician Work


- 1. Run Power to new MuTrgr FEE racks on MMS. by 10/31
- 2. Install 120 volt AC power drops into new control room annunciator alarm rack (rack room). Work in progress, to be completed by 10/15.
- 3. Re-wire ToF Rack power distribution bucket in Gas Mixing House. This is to correct minor wiring errors. By 10/31/08
- 4. Install new UPS in Gas mixing house. By 11/30
- 5. Walk down PHENIX Electrical Distribution Panels/Breakers and update changes on the electrical one-line drawings. *Complete by 11/30/08*.
- 6. Install <u>power</u> and <u>signal</u> cable tray (ceiling suspended) for new DCM rack row north of existing DCM racks. To Be Scheduled
- 7. Assist in signal and LV cable installation for MuTr/RPC upgrades as necessary. MuTrgr North Done, MuTrgr South & RPC Prototype to be scheduled
- 8. Repair Duct heaters for Control Room. To Be Scheduled before it gets cold
- 9. Upgrade power capacity of Central Magnet power distribution for future bridge rack loads.
 - a) Remove existing 15KVA transformer and install 45KVA unit.
 - b) Install new (larger size) power cable from rack room to Central Magnet distribution breaker panels.

Lower priority not required for run 9, to be scheduled when manpower available and operations & projects inconvenience are minimized

PH ENIX


1008 Building Maintenance Iss

- · Roof leak in utility bathroom at northwest corner behind tech offices.
- · Roof leak over door between rack room and assembly hall.
- New Carpet for Control Room
- Trailer bathroom slop sink (for Custodians).
- Heat wrap tape for trailer bathroom toilet drains to prevent freeze/clogging in winter.
- ·New duct heater
- ·Improved Rack Room AC performance





MuTrigger FEE South & RPC Prototype Racks





MuTrigger FEE S Rack is done.

Work on these racks is in progress





Technical Support 2008

Scheduled for 10/20-10/31



Bearing rails


Translation Bar (pushing surface) is placed here



Cabling and piping must be carefully evaluated and disconnected or allowed to travel as appropriate



(Note: DC East shown below; West is similar)



Electronics repair to be accessed in this area after DC is moved east Work permit is in progress.




Entire DC must be moved east ~10"

PH ENIX

RPC2 Prototype Installation









RPC prototypes will be ready for installation as follows: RPC3 10/13,

RPC2: 10/20




RPC2 Prototype Rack















Gas flow rack and gas lines to be taken off MuID steel and moved to crystal palace wall

Cables go under magnet to west side of pedestal




RPC2 Prototype Installation





RPC Absorber



We need 80 2x4x8 and 28 2x4xZ, where Z is 13 different lengths of varying quantities between 1-1/2" and 6-3/4"

RFQ placed with CS

J. Scott will deliver 120 2×4×8 rad clean and painted lead bricks, on skid to 1008 by 10/15

Don, Jimmy, Kenny, Carter, John and Mike L. must take TQ-LEAD1 (web course) by 10/15

Checking into lead cutting at SUNYSB

Work permit req'd





Dark Current Test Stand components received.



Gap and Module storage plan written and will be made a part of the overall RPC factory plan.



RPC group to dispose of shipping containers and left over equipment to keep storage area uncluttered.





MuTr Decapacitations

Remaining 2008 work: Station 1 South to be done ~ 12/1-12/15 simultaneously with MuTrgr South and RPC absorber installations. Will require Station 1 scaffolding on south side of CM.



(Note: picture at left is mirrorred image of scaffolding in station 1 north.)



Scaffolding Crates



Existing Crates for Sta 2/3N scaffolds are severely rotted and need to be replaced with weather resistant materials.

Sta. 1 scaffolds do not have storage crates. These need to be built of similar materials. All dimensions of crates are available.

PH ENIX

Rack Room Reorganization



Fairly accurate model of the current rack room configuration

Plumbing, HVAC and cable management, items in machine shop and items in laser room omitted



Safety, Security, etc.





Where To Find PHENIX Engineering Info



Links for the weekly planning meeting slides, long term planning, pictures, videos and other technical info can be found on the web site:

http://www.phenix.bnl.gov/WWW/INTEGRATION/ME&Integration/DRL_SSint-page.htm

10/16/08